

independent Rotax Maintenance Technician (iRMT) Rotax 912 / 914 Overhaul Course

Pre-Requisites:

- 1. Completion of a Rotax authorized 912 / 914 Heavy Maintenance Course within the last 24 months
- 2. Minimum of 5 years of hands-on experience in maintenance of Rotax 4 stroke Aircraft Engines.
- 3. In-depth Knowledge of piston powered aircraft engines.
- 4. Experience and knowledge of precision measurement equipment.
- Applicant must prove he has the facilities, tools and a requirement for overhaul training and meet pre-approval for same.

Intended Audience:

Maintenance personnel intending to perform complete tear-down Repair/Overhaul of Rotax 912 and 914 series Aircraft Engines.

5 Day hands-on course covering the following according to the Overhaul & Heavy Maintenance Manuals:

- Hands-on teardown and evaluation of 912 / 914 Series Rotax Aircraft Engine:
- · Compete disassembly including splitting case
- Proper documentation procedures
- Inspection of systems and components
- Hands on measurement and qualification of components
- Hands on re-working of all components including cylinder heads, gearbox etc.
- Hands on re-assembly of engine
- · Test run and qualifying engine
- Tips, tricks and tools of the trade

Conclusion:

At the end of this 5 day Overhaul course, the learner will have gained basic proficiency and pre-requisite experience to Overhaul a complete Rotax 912 / 914 series engine including Components.

- Certificate awarded for successful completion.
- iRMT applicants are issued an iRMT Certificate with Overhaul Rating.
- Serves as pre-requisite experience for engine type as listed in FAR 65.81.
- Serves as 40 hours of initial, recurrent or update training when and where applicable.

Fees:

912 / 914 Overhaul Course

\$ 2650.00*

Fees include necessary manuals. Applicable taxes are extra. Fees are Non-Refundable within 30 days of course dates and a \$100 cancellation fee (per course) applies if applicant cancels 30+ days of course date. Course seats can not be reserved without full payment. Travel and accommodation expenses are not included - you will need to make your own travel arrangements and a rental car may be necessary for local transportation.

Registration:

Advance registration is required. To register call 236-600-0137 or e-mail training@rotechflightsafety.ca. Include a credit card number or authorized purchase order number to confirm registration.

Location:

Courses are held at ROTECH MOTOR Ltd., 6235 Okanagan Landing Rd. Vernon, BC Canada.



ROTECH MOTOR LTD.

Authorized Rotax Training Organization 6235 Okanagan Landing Rd. Vernon, BC V1H 1M5 Telephone 236-600-0137 * Fax 236-600-0138